1,600 gallon air receiver in a fiberglass plant

State inspection and
Certification tag 5 months old

Note clean, smooth
Painted exterior

Note weld seam

Bottom of dome 20”
below weld seam

- Blow down of process piping due to rust contamination

4” pipe for
Blow down

Plume of rust
particles 2” thick

Inside view of receiver

-

Weld seam seen from manhole

Products of corrosion from lack of effective drainage fills th entire bottom c the receiver.

1,100 Gallon Receiver in a Paper Mill

8” pipe flange connection

Photo of Products of Corrosion inside the 1,100 Gallon Receiver

The weld seam in
This receiver is below
The level of rust